

Computers

	Country	Volume
Panasonic CF73 Laptop	Japan	100K
<i>Supplemental Panasonic CF73</i>	<i>China</i>	<i>500K</i>
Sony Vaio VGC-V517G	Japan	500K
Apple Mini Mac G4	China	500K
Dell Inspiron 600m	Malaysia	1.5M
E-Machines T2862	China	1M
Apple iMac G5 17"	China	250K
Apple iBook G4 - M9628LL/A	Taiwan	500K
iX104C2 Tablet PC	Taiwan	12K
Dell Axim X51 Handheld w/Pocket GPS	Korea	85K
<i>Supplemental Dell Axim X51 Handheld w/Pocket GPS</i>	<i>Korea</i>	<i>340K</i>

Credit Card Processor

	Country	Volume
Hypercom Optimum T4100	China	250K
Hypercom Optimum L4100	China	100K

Medical Field

	Country	Volume
Medtronic MiniMed 508 Insulin Pump	USA	30K

Miscellaneous

	Country	Volume
Daimler Chrysler C-Class PCB's	Germany	600K
OSI Mod-522 PCB	Mexico	20K
<i>Supplemental OSI 522 PCB</i>	<i>China</i>	<i>20K</i>
Audi A6 Door Module	Ireland	1.2M
RCA DRC247N DVD Player	China	2M
Sunbeam Bread Maker 5891	China	750K
HP Spectrophotometer	China	50K
<i>Supplemental Spectrophotometer</i>	<i>China</i>	<i>500K</i>
<i>Supplemental Spectrophotometer</i>	<i>Switzerland</i>	<i>50K</i>

MP3 Players

	Country	Volume
iRiver H320 MP3 Player	China	1M
Apple iPod Nano	China	9M
Apple iPod	China	6M
Samsung YP-55 V/XAA	Korea	2M
Creative ZEN Vision M	Malaysia	2M
JVC XA-MP51W	China	2M
Sony Walkman Bean NW-E307W	Malaysia	2M
Philips HDD1630	China	2M
Sandisk SDMX-512	China	2M

Networking & Communication

	Country	Volume
NetGear 726S 24-Port 10/100 Switch	China	28K
D-Link 3226L 24-Port 10/100 Switch	China	88K
HP 2524 24-Port 10/100 Switch	China	88K

Networking & Communication	Country	Volume
Cisco Catalyst 6509 Blade - Supervisor Engine 720	China	4K
<i>Supplemental Cisco Supervisor 720</i>	<i>China</i>	<i>15K</i>
<i>Supplemental Cisco Supervisor 720</i>	<i>Mexico</i>	<i>4K</i>
<i>Supplemental Cisco Supervisor 720</i>	<i>Mexico</i>	<i>15K</i>
Cisco Catalyst WS-X6748-GE-TX 48-port Switch	China	4K
<i>Supplemental Cisco 48-port Switch</i>	<i>China</i>	<i>15K</i>
<i>Supplemental Cisco 48-port Switch</i>	<i>Mexico</i>	<i>4K</i>
<i>Supplemental Cisco 48-port Switch</i>	<i>Mexico</i>	<i>15K</i>
Charles Step DSL ECN320 Ethernet Switch	China	4.3M
<i>Supplemental Step DSL ECN320 Ethernet Switch</i>	<i>China</i>	<i>18K</i>
Charles Step DSL EDN312 DSLAM	China	4.3M
<i>Supplemental Step DSL EDN312 DSLAM</i>	<i>China</i>	<i>360K</i>
3Com (3CR17255-91) 5500G-EI 48-Port	China	8K
3Com (3CR17172-91) Monza PWR 5500-EI 52-Port	China	8K
3Com (3CR17572-91) Buckbeak 4500 PWR 50-Port	China	10K
3Com (3CR17561-91) Buckbeak 4500 26-Port	China	10K
Qlogic SANbox 1400 Starter Kit	USA	8K
<i>Supplemental Qlogic SANbox 1400</i>	<i>USA</i>	<i>16K</i>
<i>Supplemental Qlogic SANbox 1400</i>	<i>China</i>	<i>8K</i>
<i>Supplemental Qlogic SANbox 1400</i>	<i>China</i>	<i>16K</i>
3Com (3CR17254-91) 5500G-EI 24-Port	China	4800
<i>Supplemental 3Com Switch 5500-EI PWR 52-Port</i>	<i>China</i>	<i>12K</i>
IBM TotalStorage SAN16M-2 2026-416 16-port Fabric Switch	China	8K
<i>IBM TotalStorage SAN16M-2 2026-416</i>	<i>China</i>	<i>32K</i>
<i>IBM TotalStorage SAN16M-2 2026-416</i>	<i>USA</i>	<i>8K</i>
<i>IBM TotalStorage SAN16M-2 2026-416</i>	<i>USA</i>	<i>32K</i>
IBM TotalStorage SAN16M-2 2026-432 32-port Fabric Switch	China	8K
<i>IBM TotalStorage SAN16M-2 2026-432</i>	<i>China</i>	<i>32K</i>
<i>IBM TotalStorage SAN16M-2 2026-432</i>	<i>USA</i>	<i>8K</i>
<i>IBM TotalStorage SAN16M-2 2026-432</i>	<i>USA</i>	<i>32K</i>
Nortel BCM 50 Base Unit NT9T6100 w/ethernet router	Mexico	10K
Avaya IP-Office 406V2 Office Platform	Taiwan	10K
Siemens HiPath 3300 Business Telephone System	Greece	10K
Clearwire Broadband Wireless Modem RSU-2510-FV	Taiwan	250K
Brocade NIC LPE12002	China	50K,125K,250K
HP NIC QLE2560	China	50K,125K,250K
Brocade Accton Switch	China	50K
Scientific Atlanta (Cisco) GainMaker	Mexico	25K
<i>Supplemental Scientific Atlanta (Cisco) GainMaker</i>	<i>Mexico</i>	<i>50K</i>
Scientific Atlanta (Cisco) GainMaker Transponder	Mexico	25K
<i>Supplemental Scientific Atlanta GainMaker Transponder</i>	<i>Mexico</i>	<i>50K</i>
Arris C-Cor FlexMax 901E	Mexico	25K
<i>Supplemental Arris C-Cor FlexMax 901E</i>	<i>Mexico</i>	<i>50K</i>

Phones	Country	Volume
ShoreTel IP 110 Phone	Mexico	80K
RIM Blackberry 7290 Cell Phone	Canada	100K
LG Electronics LG-KP4000 Cell Phone	Korea	250K
Toshiba 803T	Japan	250K
Nokia 8801	Korea	250K
Nokia N90	Finland	250K
Sony Ericsson W550i	China	250K
Panasonic EB-MX6	Philippines	250K
Nokia 2125	Mexico	250K
Nokia 6111	Korea	250K
Panasonic P902i	Japan	250K
Motorola PEBL U6	Hong Kong	250K
Blackberry 8700c	China	250K
Nokia 7380	China	250K
Sharp SH902i	Japan	250K
Motorola A668	Taiwan	250K
Nokia 6270	Korea	250K
NEC N902i	Japan	250K
Samsung SPH-V7900	Japan	250K
Motorola Razr V3c	China	250K
Sanyo W33SA	Japan	250K
LG SB120 Mobile Phone	Korea	250K
Motorola RAZR V3x	China	250K
Motorola RAZR V3i	China	250K
Nokia 6680	China	250K
LG U880	Korea	250K
Palm TREO 700w	Taiwan	250K
Kyocera A5515K	Japan	250K
Sharp V804SH	Japan	250K
Toshiba W41T	Japan	250K
Casio W41CA	Japan	250K
Nokia E70	Finland	250K
Nokia N91	Finland	250K
Nokia N80	Finland	250K
Motorola A732	China	250K

Printers - Barcode	Country	Volume
Avery Dennison AP 5.4 Barcode Printer	Singapore	5K

Printers - Color Laser	Country	Volume
Konica Minolta 5440DL Color Printer	China	100K
<i>Supplemental Konica Minolta 5440DL Color Printer</i>	<i>China</i>	<i>50K</i>
Konica Minolta 2400W Color Printer	China	250K
<i>Supplemental Konica Minolta 2400W Color Printer</i>	<i>China</i>	<i>50K</i>
HP CLJ 2600n Color Laser Printer	China	500K
<i>Supplemental HP CLJ 2600n</i>	<i>China</i>	<i>50K</i>

Printers - Color Laser

	Country	Volume
HP CLJ3800n Color Laser Printer	China	500K
<i>Supplemental HP CLJ3800n</i>	<i>China</i>	<i>50K</i>
Lexmark C524N Color Laser Printer	China	120K
<i>Supplemental Lexmark C524N</i>	<i>China</i>	<i>50K</i>
HP CLJ4700n Color Laser Printer	Japan	500K
<i>Supplemental HP CLJ4700n</i>	<i>China</i>	<i>50K</i>
Samsung CLP-600n Color Laser Printer	Korea	40K
<i>Supplemental Samsung CLP-600n</i>	<i>China</i>	<i>50K</i>
Xerox Phaser 7760DN Color Laser Printer	China	24K
<i>Supplemental Xerox Phaser</i>	<i>China</i>	<i>50K</i>
HP CLJ 5550n Color Laser Printer	Japan	100K
<i>Supplemental HP CLJ 5550n</i>	<i>China</i>	<i>50K</i>
Xerox Phaser 6300n Color Laser Printer	China	100K
<i>Supplemental Xerox Phaser 6300n</i>	<i>China</i>	<i>50K</i>
Konica Minolta magicolor 2480MF Color Laser Printer	China	350K & 50K
<i>Supplemental Konica 2480F</i>	<i>China</i>	<i>50K</i>
HP CLJ 2840 Color Laser Printer	China	140K
<i>Supplemental HP CLJ 2840</i>	<i>China</i>	<i>50K</i>
Dell 3110cn Color Laser Printer	China	125K
<i>Supplemental Dell 3110cn</i>	<i>China</i>	<i>50K</i>
HP CLJ 1600 Color Laser Printer	China	225K
Lexmark C770n Color Laser Printer	China	25K
<i>Supplemental Lexmark C770n</i>	<i>China</i>	<i>50K</i>
Samsung CLP-300 Color Laser Printer	Korea	300K
Ricoh C410DN Color Laser Printer	China	25K
<i>Supplemental Ricoh C410DN</i>	<i>China</i>	<i>50K</i>
Brother MFC-240c Color Laser AIO Printer	China	500K
Samsung CLX-3160FN Color Laser AIO Printer	Korea	300K & 40K
<i>Supplemental Samsung CLX-3160FN</i>	<i>China</i>	<i>50K</i>
Brother HL-4040cn Color Laser Printer	China	400K
<i>Supplemental Brother HL-4040cn</i>	<i>China</i>	<i>50K</i>

Printers - Dot Matrix

	Country	Volume
Epson LX-300+	Indonesia	200K
<i>Supplemental Epson LX-300+</i>	<i>Indonesia</i>	<i>660K</i>

Printers - Inkjet

	Country	Volume
HP PhotoSmart 8250	Malaysia	500K
Lexmark Z735	China	2M
Canon Pixma MP150	Vietnam	1.2M
HP Deskjet 6940	Malaysia	335K
HP PSC 1610 All-in-One	Malaysia	1.2M
HP Deskjet 5440 Photo Printer	Thailand	700K
Epson Stylus C88 Inkjet Printer	Indonesia	160K
Epson Stylus CX4800 AIO Printer	Thailand	300K

Printers - Inkjet

	Country	Volume
Lexmark X8350 AIO Inkjet Printer	Vietnam	195K
HP OfficeJet 5610 AIO Inkjet Printer	China	300K
Epson Stylus CX5800 AIO Inkjet Printer	China	100K
Kodak Easyshare 5100 AIO Printer	China	500K
Kodak Easyshare 5300 AIO Printer	China	500K
HP OfficeJet Pro L 7580 AIO Color Printer	China	250K
<i>Supplemental HP OfficeJet Pro L7580 AIO</i>	<i>China</i>	<i>1M</i>
HP OfficeJet Pro K5400tn Color Printer	China	250K
<i>Supplemental HP OfficeJet Pro K5400tn</i>	<i>China</i>	<i>1M</i>
Memjet Proprietary Full width Office Printer	China	480K
HP 8600 Pro	China	2.5M
Epson WorkForce 845	Indonesia	545K
Lexmark PRO715	China	150K
HP OfficeJet 150 Mobile	Malaysia	150K

Printers - LED

	Country	Volume
Xerox Phaser 7400n Color LED Printer	China	24K
<i>Supplemental Xerox Phaser 7400n</i>	<i>China</i>	<i>50K</i>
Oki C3400n Color LED Printer	Thailand	180K
<i>Supplemental Oki C3400n</i>	<i>China</i>	<i>50K</i>

Printers - Mono Laser

	Country	Volume
Brother HL2040	China	1M
HP LJ 2430n	China	1M
<i>Supplemental HP LJ 2430n</i>	<i>China</i>	<i>50K</i>
Brother MFC 7420	China	Various
<i>Supplemental Brother MFC 7420</i>	<i>China</i>	<i>50K</i>
Dell 1100 Laser Printer	China	2.3M
<i>Supplemental Dell 1100 Laser Printer</i>	<i>China</i>	<i>50K</i>
Samsung SCX-4521F	China	500K & 2.8M
<i>Supplemental Samsung SCX-4521F</i>	<i>China</i>	<i>50K</i>
Samsung ML-3561N	Korea	70K
<i>Supplemental Samsung ML-3561N</i>	<i>China</i>	<i>50K</i>
Lexmark E120n	China	350K
<i>Supplemental Lexmark E120N</i>	<i>China</i>	<i>50K</i>
Canon MF-3240	China	300K
<i>Supplemental Canon MF-3240</i>	<i>China</i>	<i>50K</i>
Brother HL- 5240	China	800K
<i>Supplemental Brother HL-5240</i>	<i>China</i>	<i>50K</i>
Brother MFC-8460N Multifunction Laser Printer	China	800K & 150K
<i>Supplemental Brother MFC-8460N AiO</i>	<i>China</i>	<i>50K</i>
Lexmark T642n Laser Printer	China	150K

Printers - Mono Laser

	Country	Volume
<i>Supplemental Lexmark T642n</i>	<i>China</i>	<i>50K</i>
Samsung SCX-4200 Mono Laser Printer	China	1.15M & 750K
<i>Supplemental Samsung SCX-4200</i>	<i>China</i>	<i>50K</i>
HP LJ 1018 Laser Printer	China	1.1M
Lexmark E342n Mono Laser Printer	China	1.5M
<i>Supplemental Lexmark E342n</i>	<i>China</i>	<i>50K</i>
HP LJ 4250n Laser Printer	China	588K
HP LJ 1320tn Laser Printer	China	500K
<i>Supplemental HP LJ 1320tn</i>	<i>China</i>	<i>1M</i>
<i>Supplemental HP LJ 1320tn</i>	<i>China</i>	<i>1.5M</i>
HP LJ P3005 Laser Printer	China	900K
<i>Supplemental HP LJ P3005</i>	<i>China</i>	<i>50K</i>
Canon imageClass MF4150 Multifunction Laser Printer	Korea	500K & 100K
<i>Supplemental Canon imageClass MF4150</i>	<i>China</i>	<i>50K</i>
Lexmark E350d Mono Laser Printer	China	1M & 240K
<i>Supplemental Lexmark E350d</i>	<i>China</i>	<i>50K</i>
Xerox Workcentre 4150/S Mono Laser AIO Printer	Korea	50K
<i>Supplemental Xerox 4150/S</i>	<i>China</i>	<i>50K</i>
Lexmark x646e MFP Mono Laser AIO Printer	China	340K
<i>Supplemental Lexmark x646e</i>	<i>China</i>	<i>50K</i>
Samsung ML 3051ND Mono Laser Printer	Korea	300K & 40K
<i>Supplemental Samsung ML 3051ND</i>	<i>China</i>	<i>50K</i>
Samsung ML-2510 Mono Laser Printer	China	2.5M
<i>Supplemental Samsung ML-2510</i>	<i>China</i>	<i>50K</i>
Okidata B2500MFP Mono Laser All-in-One Printer	China	300K

Printers - Thermal Transfer

	Country	Volume
Zebra LP 2844-Z	Taiwan	21K
Intermec Easy Coder PC4	Taiwan	21K
Zebra S-600	Taiwan	2.4K
Intermec PD4	Taiwan	2.4K
Zebra Z4Mplus	USA	9.6K

Projectors

	Country	Volume
Samsung SP-P9300ME Pocket Projector	Korea	300K
<i>Supplemental Samsung SP-P9300ME Pocket Projector</i>	<i>China</i>	<i>120K</i>

Scanners

	Country	Volume
HP 9200C Digital Sender	China	15K
<i>Supplemental HP 9200C Digital Sender</i>	<i>China</i>	<i>50K</i>
Metrologic Eclipse MS5145 Bar Code Scanner	China	600K
Metrologic QunatumT MS7120 Bar Code Scanner	China	100K
PSC Magellan 2200VS Bar Code Scanner	Malaysia	100K